

## Sales information

### Only available from MEYLE: Mercedes Benz glow plug control unit kit including glow plugs

Control unit failure is usually caused by a defective glow plug, in which case, only replacing the control unit will not remedy the problem. On the contrary: the defective glow plug is likely to damage the new control unit too. This is why vehicle manufacturers always replace the control unit along with the glow plugs.

The following kits are currently available:

MEYLE no. 014 880 0010/S incl. 6 glow plugs to fit Mercedes-Benz E300



MEYLE no. 014 880 0007/S incl. 4 glow plugs to fit Mercedes-Benz C- and E-Classes, CLC, Sprinter, Viano and Vito



Also available: MEYLE no. 014 880 0008/S  
incl. 4 glow plugs to fit Mercedes-Benz C- and E-Classes

MEYLE no. 014 880 0011/S incl. 5 glow plugs to fit Mercedes-Benz C-, G-, E-, and M-Classes, CLK and Sprinter



Also available: MEYLE no. 014 880 0012/S  
incl. 6 glow plugs to fit Mercedes-Benz S-Class

MEYLE no. 014 880 0015/S incl. 6 glow plugs to fit Mercedes-Benz G-, E- and S-Classes, Puch G-Model



Also available: MEYLE no. 014 880 0014/S  
incl. 5 glow plugs for Mercedes-Benz C- and E-Classes  
MEYLE no. 014 880 0013/S incl. 5 glow plugs for Mercedes-Benz E- and G-Classes, Vario, Sprinter and Unimog



When replacing glow plug control units and glow plugs follow the manufacturer's specifications at all times.