



MEYLE[®]
Products

MEYLE No.
100 710 0005/HD

Reference No.
1K0 407 183 E
6Q0 407 183 A

Mount, control arm

to fit

**Seat Cordoba, Ibiza IV, Skoda Fabia, Skoda Roomster,
VW Fox, VW Polo**



as OE

Problem

Rubber bearing does not provide enough cornering force and can wear out very quickly

Effect

Steering play, accurate lateral guidance no longer possible



Solution



Reinforcement of the critical rubber dimensions for enhanced bonding of the inner control arm mount to the outer sleeve

Advantage

An improved component with a longer service life

as OE



MEYLE version

